

JOHN DEERE 4730

602518

Price: \$ 145,000

Price Including GST: \$ 159,500

Serial No. N04730X004531 **Engine No.** PE6068L061338

Engine Hours: 6,188

2008 Model, A/C Cab, 90' Boom, 3000L Tank, 2600 Display, 50 CM Nozzle Spacings, Stainless Steel Eductor, Hydraulic Tread Adjust, Traction Control, Boom Return to Height, Belly Shields, Wheel Motor Shields, Field Vision Xenon HID Lights.

Front 420/80R X 46 Tyres 40% Rear 420/80R X 46 Tyres New 100%

REPAIRS

Removed all the plumbing from the left and right booms. Removed the breakaway and outer boom sections. Removed the main boom sections and sent to be repaired. Refitted the main boom sections. Fitted the outer boom and new breakaways. Refitted some of the plumbing to the booms. Hot wash, degrease and clean machine. Replaced R/H rear ride height valve. Replaced stabilizer links that were missing. Replaced damaged L/H breakaway cylinder lines. Removed L/H lift cylinder & fitted a seal kit. Refitted cylinder. Remove tank gauge & support, repair support & fit new tubing for gauge. Tidy up wiring, run hoses back through booms. Decontaminate & boom. detail cab, clean windows, fit PVM & safety decals. Refit all removed panels & guards. Weld up cracks in front diff. Replace both front & rear wheel guards. Jacked up machine, removed R/H rearwheel. Drained hub oil & removed hub plate. Drilled out & removed hub retainer nut & pulled hub apart. Found that the bearings were damaged. Organised new bearings. Installed new bearings & seals & reassembled the hub with a new retainer nut. Refitted hub & wheel. Replaced R/H rear brake pads. Replaced broken fuel cap. Replaced both front air bags & replaced hydraulic tank sight glass. WW Service Invoice # 2319066, Cost \$ 20,123. Wee Waa Service Invoice # 2335249, Cost \$ 19,994. Total Cost \$ 40,417.

LOCATED WEE WAA