



JOHN DEERE 8360R

602774

Serial No. 1RW8360RADD071379
Engine No. RG6090G012023

Price: \$ 170,000
Price Including GST: \$ 187,000

4,946 Hours

360 Horsepower

2013 Model, MFWD with ILS, IVT Transmission, Premium Radio, 3PL, Autotrac Ready, Front Fenders, HID Lights, 4 Remotes, Radar, Base + 22 Nose Weights, Inner Wheel Weights. Cotton Reel Spacers for 3M.

Single Front 480/70RX34 Tyres 50%
Dual Rear 480/80RX50 Tyres 100/90% IS, 20%/TBA OS

RECENT REPAIRS

RO #	Date	Description	Hours	Cost
2302569	11/01/17	Alter wheel spacing to 3 metres with supplied components. Clean/ Remove corrosion from spacers, bolts and threads. Jack and support machine. Remove rear wheels and swap right hand - light hand/ light hand - right hand. Adjust and tighten to correct spacing. Remove front wheels drain oil from left hand / right hand final drives. Check condition of old oils and refill to spec with new oil. Alter dish configuration of both wheels. Install adapters, rings, spacers and torque to spec. Adjust steering cylinder stops. Run machine. Drive for 15 minutes and recheck torque of wheel bolts.	2487	\$ 893
2315314	20/04/17	PIP No. 16RW654A Failed Part No. MPR12982 Correction: As per installation instructions R557396 split tractor at engine/transmission. Remove transmission assembly. Evacuate and recover R134A refrigerant gas from air-conditioning system. Purge and flush air-conditioning system. Remove old receiver dryer. Carry out disassembly of IVT transmission. Fit updated components and reassemble. Refit IVT into tractor. Refit engine. Refill hydraulic oil. Fit new receiver dryer to air-conditioning system. Vacuum air-conditioning system. Charge air-conditioning system with recovered R134A gas. Check and run air-conditioning system for leaks - none found. Run and test operation of tractor.	2892	\$ 7,351
2315503	21/04/17	Perform 3000 hour service. Drain rear axle, IVT transmission, front ILS reservoir for hydraulic oil. Change hydraulic oil filters. Drain and replace engine oil, change engine oil filter. Change fuel filters. Install new air filters, wipe out housing with damp rag. Remove tappet cover, adjust valve clearances, clean up sealing surfaces. Install new gasket and tappet cover. Torque bolts in sequence. Check belts - OK. Clean out cooling package. Graese machine. Run and check for leaks - all OK. Top up coolant levels.	2892	\$ 2,897
2373598	12/12/18	Check operation of air-conditioning system. Found compressor faulty. Evacuate and recover R134A gas from system(no gas left). Remove air-conditioning compressor. Purge and flush air-conditioning system. Remove old receiver dryer and fit new receiver with new orings. Remove cab filter and clean with compressed air. Clean condensor. Fit new air-conditioning compressor. Vacuum air-conditioning system. Add dye solution. Charge air-conditioning system with R134A gas. Check air-conditioning system for leaks. Run air-conditioning system and check for leaks.	4503	\$ 2,267

LOCATED QUIRINDI

REPAIRS

Inspect machine & locate any fluid leaks. Remove bewy plates, engine guards. Blow / wash out dirt & cotton debris. Unbolt bonnet & roll forward, remove clamps & leaking pipe (ivt to oil cooler). Install new pipe & o'rings, reassemble clamps. Remove ILS accumulators x 4, test pressures all below 20%. charge new accumulators to spec with nitrogen & install with new o'rings. Dissassemble RH lower ILS ball joint & replace lower boot, reassemble. Replace LH & RH inner tie rod ball joints, grease. Repair damaged ILS solenoid harness (LH Lower) , remove engine fan shroud, fan & belt. Grease fan sheaves, install new belt & reassemble fan / ducting & shroud. Drain coolant & replce lower radiator hose. Replace rear window latch / handle & weatherstrip. Remove rear wiper arm & replace as spline chewed out. Replace broken SCV covers. Drain hydraulic oil from diff / IVT & clean oil reservoir. Remove leaking pipe (clean oil Res. to hyd. pump) & replace o'rings & refit. Replace leaking park brake solenoids x 2. Disconnect & remove battery's, remove debris from battery box. Check electrolyte levels & top up, reinstall battery's. Repair washer bottle water hose (rodent damage). Drain engine oil & remove filter / fuel filters, drain / dissassemble water sedimenter & clean out debris. Replace oil & fuel filters, fill with oil & bleed fuel system. Refill engine coolant. Change hydraulic filters & refill hydraulics & IVT to level, run machine & rechack. Remove front wheels / spacers, drain front hubs & refill with fresh oil, reinstall wheels / spacers & tension bolts to spec. Change engine air filters & cabin fresh air filters. Dissassemble steering column & replace pivot bushes, reassemble. Replace front grille lwr weatherstrap. Refit front weight bracket & weights. Replace rear window main weatherstrip. Remove roof, remove damaged nutserts for greenstar bracket & replace. Strip out mats / seat covers from interior. Wash out tar stained headlining (twice). Wash machine, detail, paint & polish. Grease suspension & linkage points. Quirindi Service Invoice 2387512, Cost \$ 13,765.